## Qualitative Monitoring **Fish Passage at Crossings** Codes CDFG - CRMEP June 2006 Draft

ALN	Alignment problem	OTH	Other
APP	Approach problem	OVT	Overtopped
ARM	Armoring	PAR	Partial barrier
BAR	Lack of stabilizing vegetation	PIP	Piping
BNC	Benching	PLA	Plastic
CGA	Culvert Gravel Absent	PLG	Plug potential
CHIN	Chinook salmon	PLN	Planting
CNR	Concentrated runoff	RBK	Right bank
СОНО	Coho salmon	REP	Repair
COM	Compacting	RRG	Other road-related gullying
COM	Concrete	SBE	Streambank erosion
COR	Corroded	SBL	Streambank landslides
CRS	Crushed	SCW	Stream crossing washouts (gullies)
CT	Cutthroat trout	SEU	Seeding
CUT	Road cutbank failures	SEE	Surface erosion
DBB	Debris barrier	SH	Steelhead trout
DBR	Debris	SLA	Fillslope angle problem
DIV	Stream diversion	SLA	Silt fence
DNS	Downstream	STM	Straw mulch
DSP	Downspout	SUB	Substrate
EFL	Earthflows and large,	TEM	Temporal barrier
	slow moving landslides	TOT	Total barrier
EMG	Emergent groundwater	UND	Undercut/Undermined
ENH	Enhancement	UNS	Undersized
FJH	Fish jump height	UPS	Upstream
FLA	Flared inlet	USG	Unstable soils/geology
FLS	Road fillslope failures		Wingwalls
GRC	Grade control structure	WIN	Within
GRZ	Grazing/grazing animal	WOO	Wood
HIG	High potential	WSH	Washed out
HYD	Hydrologic processes		Water depth
LAN	Landing failures	WTR	Water
LBK	Left bank	WTV	Water velocity
LOW			ssage improvement at stream crossings (other)
MIT	Mitered inlet	151 151 pa	Bridge installation or replacement
MNT	Maintenance	151	Embedded culvert installation or replacement
MOD	Moderate potential	152	Bottomless arch culvert installation or replacement
MTL	Metal	155	Other culvert installation or replacement
NON	None	155	Grade control weirs associated with a HB structure
NRG	Non-road gullying	155	Engineered roughened channel associated with a HB structure
NRL	Non-road (hillslope) debris landslides	157	Steam crossing decommission for fish passage
NRP	No resting pool	121	Back flooding weir associated with a HB structure
NTG			modification (other)
NTM	Native Mulch	122	Culvert baffles (other)
NTR	Native rock	122	Washington baffles
OFR	Off-site rock	123	Steel ramp CMP baffles
0110	on the rock	147	Such tamp on the burnes