

Cultural and Historic: Contact the Southwest Information Center at (657) 278-5395.

Response Strategy Site: BNSF Maintenance Yard (CAJ-020)

Site Description and Field Notes							
River Width:	Site Location/Segment: CAJ-SR-A-003						
115 meters (377 feet)							
Gradient: Low Slow	Strategy/response will depend on water flow. There is a manmade structure on the southeast edge of the riverbank.						
	A roadway leads into the stream. Large staging area.						
Site Contact/s:							
	Vehicular Access: 4WD Pick-Up						
BNSF - (800) 832-5452	Recreational Use: N/A						
	Recreational Use: N/A						
UPRR - (888) 877-7267	Boat Launches: N/A						
	ESI Shoreline Type: 1B Exposed, solid man-made structures; 3A Fine to medium-grained sand; 4 Sandy bars and						
	gently sloping banks						
1							

Site Images





Page 2 of 3

Upstream

Downstream



Straight Across

Photo Date: 12/28/2017

Response Strategy Site: BNSF Maintenance Yard (CAJ-020)

Page 3 of 3

Site Objectives: Earthen berm/underflow dam to prevent further movement of oil down gradient and collection of oil.

Implementation: Minimize ingress and egress routes through vegetation to prevent erosion and disturbance of the surrounding ecosystem. Weather and water flows will determine specific site strategies.

Staging Area Location and Capabilities/Amenities/Waste Management: Large staging area.

Response Strategy Map (overview)



Table of Response Resources							
Туре	Sub-Type	Size	Unit	QTY - Unit	Special Equipment or Comments		
Backhoe					For earthen berm/underflow dam		
Piping					For earthen berm/underflow dam		