4-607-A Site Summary - Arroyo Hondo Preserve & Creek

County: Santa Barbara **ACP Division/Segment:** SB - I - S03

NOAA Chart: 18721 **Map Book:** 3653 X 7 **Decimal Degrees:** 34.474 -120.141

Site Description:

This creek is owned by the Land Trust for Santa Barbara County. For a marine spill the risk area extends upstream to the upper reaches of the tidal influence. For an inland spill the risk extends upstream highway 101 to the oil pipeline crossing of the watershed. There is also a natural gas line that crosses the creek. The railroad trestle also crosses the creek mouth, lagoon and marsh. To the east and west of the creek mouth are cobble beaches. Two striped garter snakes, shorebirds and waterfowl are present. There is evidence of deer, bear and mountain lions in the upper portions of the watershed. Intermittent coastal wetland, esturary and riparian habitat are present.

Resources at Risk:

ESI and Habitat: 10A Salt - and brackish-water marshes

9B Vegetated low banks

5 Mixed sand and gravel beaches

3A Fine- to medium-grained sand beaches

List of Resources at Risk:

	Resource Name	Status	Presence	Sensitivity
Amphibians	California red-legged frog	FT, SSC	Year-round	
Fish	tidewater goby	FE, SSC	Year-round	
Fish	steelhead - Southern California	FE	Year-round	
Mammals	Southern sea otter	FT, SP	Year-round	
Reptiles	southwestern pond turtle	SSC	Year-round	

FT-Federally Threatened, FE-Federally Endangered, FP-Federally Protected, SE-State Endangered, ST-State Threatened, SP -State Protected, SR-State Rare, SSC-Species of Special Concern, BGEPA-Bald and Golden Eagle Protection Act, SSSP-State Special Status Species

List of Key Contacts:

Type Name/Title		Organization	Phone	
С	/	Central Coast Information Center	(805) 682-4711	
С	/Coordinator	Native American Heritage Commission	(916) 373-3710	
Ε	/Preserve Manager	Arroyo Hondo Preserve	(805) 567-1115	
Ε	/Land Manager	Land Trust for Santa Barbara County	(805) 966-4520	
Т	Kyle Evans/Steelhead	California Department of Fish & Wildlife	(805) 794-9547	
Т	SURCOM (24-hr)/	California State Parks (Dispatch)	(951) 443-2969	
Т	/Spill Response Coordinator	US Fish and Wildlife Service, Federal T&E Species	(805) 644-1766	

C – Cultural, Historic, Archaeological; E – Entry/Owner/Access; O – Other; S – Safety; T – Trustee; X – Exclusion or Security

Additional Site Summary Comments:

4-607-A

Concerns and Advice to Responders:

The lagoon and stream provide habitat for both sensitive and T/E species which can be killed or injured by oil and response/cleanup activities unless responders minimize disturbance in stream, lagoon and associated vegetation and avoid trampling oil into sediments; and follow protective conditions from IC and resource biologists. There is a beach gate to provide access to the estuary and the code is 1963. Access for the estuary is through a pathway on the east side of the creek. Carrying equipment along the pathway could be hazardous.

Hazard and Restrictions:

Unhealthy levels of coliform bacteria have been found intermittently in streams and on beaches in this area. Use appropriate PPE, safety procedures, and include reference to potential health problems in any site safety plan.

Site Strategies: Site Validation Level: V

Strategy: 4-607.1 Objective: Exclude Oil

Strategy: Deploy exclusion booms across the inlet to minimize the likelihood of oiling the estuary. Place the booms in a configuration that forms an adjustable oil collection pocket that can accommodate changes in flow direction. Back exclusion booms with sorbent booms to minimize leakage. Line the shorelines and any side channels within the inlet to prevent collateral oiling. If there is recoverable oil on-water, deploy sorbents and contact the IC immediately regarding the use of skimmers. Monitor, adjust, and replace booms as needed to maintain effectiveness.

Table of Response Resources

Equipment	Sub-Type	Size Unit	QTY Unit	Last Page Update
Boom	Swamp Boom		300 feet	Strategy Updated:
Boom	Sorbent Boom		300 feet	Last Test: 5/21/2015
Anchor			2	
Staff			5	
Vehicle	ATV		1	

Strategy: 4-607.2 Objective: Erect Filter Fence

Strategy: Construct a filter fence across the front of the channel where the inlet is narrowest, water flows are low or dry, the ground can receive and hold metal stakes, and the spill is heavy oil. Monitor barrier and replace pom-poms as necessary to maintain effectiveness.

Table of Response Resources

Table of Responde Resour				_
Equipment	Sub-Type	Size Unit	QTY Unit	Last Page Update
Fence	Construction Fencing	4 x 100 feet	2 Rolls	
Misc.	Oil Snare (pom-pom)		360	
stakes	T-posts		20	
Stake driver			1	
Staff			5	
Vehicle	ATV		1	

Strategy: 4-607.3 Objective: Shoreline Pre-Clean: Resource Specialist Supervision Required Strategy: Consult with resource trustees regarding wildlife issues before undertaking this activity. Hand crews to move and store kelp, driftwood, vegetative debris, trash, and other materials above high-tide line. Dispose of trash. Replace unoiled debris in its former location once the threat of oiling is past.

Table of Response Resources

Equipment	Sub-Type	Size Unit	QTY Unit	Last Page Update
Misc.	Trash Bags			-
Staff			5	
Vehicle	ATV		1	

Logistics:

Directions: Traveling north on highway 101, the preserve is approximately 23 miles past La Cumbre Road overpass. Approximately 5 miles past Refugio State Beach look for Call Box #101-402 and then after that Call Box #101-412. The driveway is adjacent to Call Box #101-412. Make a sharp right turn from the highway into the preserve driveway. If the gate is open, come down the driveway, cross the bridge and park by the barn. To Get Back to Santa Barbara: From the top of the driveway, turn right (north). Go 3 miles and exit at Mariposa Reina. Go over the bridge and enter the southbound on-ramp. Traveling south on Hwy. 101, approximaetly 6 miles past Gaviota State Park and 1/4 mile after the Vista Rest Area, make a U-turn at the Tajiguas Landfill into the northbound lands of Hwy. 101. In a 1/2 mile, make a sharp right turn into the Preserve driveway immediately after the Call Box #101-412.

Land Access: Access to this site is controlled by the Land Trust for Santa Barbara County.

On-Water Limitations: Santa Barbara Harbor is the nearest full service civilan harbor for berthing, launching and fueling. Facilities, Staging Areas, Command Posts, Available Equipment: There is a good amount of parking at the entrance of the reserve.

Communications Problems: none

