
Response Strategy Site: 138 Crossing (CAJ-010) Page 1 of				
Latitude: 34.311865 Longitude: -117.479304	Driving Directions			
Highway Post Mile: SDB-138-15	From North I-15, take the exit for Hwy.138, turn left and cross over the freeway, turn right on Cajon Blvd, directly after Union 76 station. Small staging area.			
Railroad Milepost: N/A	From South I-15 take the exit for Hwy.138, keep right off the freeway turn right on Cajon Blvd, directly after Union 76 station. Small staging area.			
Nearest Address and Thomas Guide #: 14757 State Hwy. 138, West Cajon Valley				
4734 C-1				
Cell Service: Yes				

Overview Street Map



Hazards, Restrictions and Advice for Responders

- High traffic area
- Strategy/Response will depend on water flow
- Rattlesnakes

Resources-At-Risk (Site and Downstream)

Ecological: Arroyo Toad, short-joint beavertail, Two-striped Garter Snake

Economic: N/A

Tribal: Contact the Native American Heritage Commission at (916) 373-3710. **Cultural and Historic:** Contact the Southwest Information Center at (657) 278-5395.

Response Strategy Site: 138 Crossing (CAJ-010)

Page 2 of 3

Site Description and Field Notes

River Width: 57 meters (187 feet) Gradient: Low Slow Site Location/Segment: CAJ-SR-A-002

Access down riprap side on east side, dirt embankment on the west.

Site Contact/s: N/A

Vehicular Access: 4WD Pick-Up

Recreational Use: N/A Boat Launches: N/A

ESI Shoreline Type: 1B Exposed, solid man-made structures; 3B Exposed, eroding banks in unconsolidated

sediments; 5 Mixed sand and gravel bars and gently sloping banks


Site Images





Upstream

Downstream



Straight Across

RR = River Right RL = River Left

Photo Date: 12/28/2017

Site Objectives: Earthen berm/underflow dam to prevent further movement of oil down gradient and collection of oil.

Implementation: Minimize ingress and egress routes through vegetation to prevent erosion and disturbance of the surrounding ecosystem. Weather and water flows will determine specific site strategies.

Staging Area Location and Capabilities/Amenities/Waste Management: Small staging area adjacent to bridge. State Cal-Trans facility adjacent to the bridge.

Response Strategy Map (overview)



Table of Response Resources						
Туре	Sub-Type	Size	Unit	QTY - Unit	Special Equipment or Comments	
Backhoe					For earthen berm/underflow dam	
Piping					For earthen berm/underflow dam	