2-712-A Site Summary - Winter Island

County: Contra Costa ACP Division/Segment: CC - I - S023 CC - I - S025

Map Book:

NOAA Chart: 18656 Suisun Bay

Decimal Degrees: 38.042834 -121.849541

Site Description:

This site includes the leveed island, surrounding berm and channel islands and the accreting, unleveed saltmarsh at the northern tip (Point San Joaquin) and the mudflats to the west of the tip. Winter island is flooded in the interior and has unregulated exchange though a tide gate. The interior of the island is emergent tule salt-marsh. The levees and surrounding berm and channel islands are vegetated with scrub and emergent marsh; most are suffering from wave erosion. The northern tip (Point San Joaquin) is an accreting emergent salt-marsh. This tip and the pocket at the northwest end of the main island are natural wind catchment sites.

Resources at Risk:

ESI and Habitat: 10A Salt - and brackish-water marshes

9B Vegetated low banks

9A Sheltered tidal flats

List of Resources at Risk:

	Resource Name	Status	Presence	Sensitivity
Birds	California black rail	FP, ST	Year-round	Mar-Aug
Fish	longfin smelt	ST	Year-round	Nov-May
Fish	steelhead - Central/Northern California	FT	Year-round	Nov-Apr
Fish	delta smelt	FT, SE	Year-round	Mar-May
Mammals	salt-marsh harvest mouse	FE, SE	Year-round	
Plants	Mason's lilaeopsis	SR	Year-round	Apr-Nov
Plants	Delta tule pea	SSSP	Year-round	May-Jul
Reptiles	giant garter snake	FT, ST	Year-round	Jul-Oct

FT-Federally Threatened, FE-Federally Endangered, FP-Federally Protected, SE-State Endangered, ST-State Threatened, SP -State Protected, SR-State Rare, SSC-Species of Special Concern, BGEPA-Bald and Golden Eagle Protection Act, SSSP-State Special Status Species

List of Key Contacts:

Туре	Name/Title	Organization	Phone
С	/Coordinator	Native American Heritage Commission	(916) 373-3710
С	/Coordinator	Northwest Information Center	(707) 588-8455
S	/Dispatch, 24-hr	Contra Costa County Office of the Sheriff	(925) 646-2441
Т	/Environmental Program Manager	CA Dept. of Fish & Wildlife, Bay Delta Region	(707) 576-2837
Т	/Agency Representative	NOAA National Marine Fisheries Service	(707) 575-6050
Т	/Restoration Ecologist	US Department of Agriculture	(530) 304-2304
Т	/Spill Response Coordinator	US Fish and Wildlife Service, Bay-Delta Office	(479) 233-9241

C – Cultural, Historic, Archaeological; E – Entry/Owner/Access; O – Other; S – Safety; T – Trustee; X – Exclusion or Security

Additional Site Summary Comments:

2-712-A Site Strategy - Winter Island

Concerns and Advice to Responders:

Emergent wetlands are extremely vulnerable to oil and very difficult to clean. Potential for oil penetration into mudflats and berms via animal burrows.

Hazard and Restrictions:

Vessels beware of submerged hazards and shallows at margins.

Site Strategies:

Site Validation Level: II

Strategy: **2-712.1** *Objective:* Extend exclusion-deflection chevron to fend past Pt. San Joaquin Marsh and Mudflats from oil threats from the west

Strategy: Deploy 3500 ft. of 9x9+ Hboom from the tip of Pt. San Joaquin westerly along the 4 ft. depth contour at the north westerly margin of the mudflat. Deploy a second 2500 ft. of 9x9+ Hboom leg from the collection pocket east of the mouth of middle slough (2-710 see Browns Island) northwest to connect with the first boom leg.

Table of Response Resources

Equipment	Sub-Type	Size Unit	QTY Unit	Last Page Update
Boom	Harbor	9x9 inch	6000 feet	
Anchor	Danforth	22 lb	13	
Vessel	Boom Boat		2	
Vessel	Skiff or Punt		1	
Staff	Staff to Deploy		8	_

Strategy: **2-712.2** *Objective:* Exclusion for oil threats from east- exclude oil entry to north cross channel and easterly barrow channel with small boom segments.

Strategy: Block openings to small channels with exclusion boom segments.

Table of Response Resources

Equipment	Sub-Type	Size Unit	QTY Unit	Last Page Update
Boom	Swamp	6x6 inch	700 feet	
Anchor	Danforth	22 lb	4	
Vessel	Boom Boat		1	
Vessel	Skiff or Punt		1	
Staff	Staff to Deploy		5	_

Logistics:

Directions: No land Access. Water access: Winter Island is a mile east of Pittsburg Marina and a mile west from Antioch Marina.

Land Access: Access by vessel only.

On-Water Limitations: Very shallow near shoreline, expect submerged obstacles. Boat launch nearby at Pittsburg and Antioch Marinas, and at public ramps.

Facilities, Staging Areas, Command Posts, Available Equipment: Good staging and facilities at both Antioch and Pittsburg marinas.

Communications Problems: Good cell reception.

