

6-470-A Site Summary - Tijuana River**6-470-A****County :** San Diego **ACP Division/Segment :** SD - O - S007 SD - O - S008**NOAA Chart :** 18772 **Map Book :** 1349 F4 **Decimal Degrees** 32.55676 -117.13026**Site Description:**

This site is within the following Marine Protected Area: Tijuana River Mouth Marine Conservation Area, and is governed by special protections established by the CDFW Marine Region. The Tijuana River and the Tijuana Slough Complex form a large wildlife preserve. Caution should be exercised to limit impact to Western snowy plover and California least tern nesting areas on the beach dunes and beach. There is also a dune restoration project in the area. Cleanup crews should be cautioned about potential water quality biohazard from sewage contamination.

Resources at Risk:

ESI and Habitat: 10A Salt - and brackish-water marshes
3A Fine to medium-grained sand beaches

List of Resources at Risk:

	Resource Name	Status	Presence
Birds	Belding's savannah sparrow	SE	Year-round
Birds	California least tern	FE, SE	Feb - Sep
Birds	light-footed Ridgway's rail	FE, SE	Year-round
Birds	Western snowy plover	FT	Year-round
Plants	intertidal mudflat		Year-round
Plants	salt marsh bird's beak	FE, SE	Variable
Plants	pickleweed		Year-round

FT-Federally Threatened, FE-Federally Endangered, FP-Federally Protected, SE-State Endangered, ST-State Threatened, SP -State Protected
SR-State Rare, SSC-Species of Special Concern, BGEPA-Bald and Golden Eagle Protection Act, SSSP-State Special Status Species

List of Key Contacts:

Type	Name/Title	Organization	Phone
C	Dr. Seth Mallios/	South Coastal Information Center	(619) 594-5682
T	Clay Phillips/	Border Field State Park	(619) 575-3613
T	/Southern Comms. Center (SURCOM) 24-hr	CA State Parks	(951) 443-2944
T	/Refuge Manager (Ext. 302)	S.D. Bay N.W.R	(619) 575-2704
T	/Reserve Manager (ext. 303)	Tijuana River NERR	(619) 575-3613
T	On Call/Spill Coordinator	US Fish Wildlife Service Carlsbad 24 hour	(760) 607-9768

C – Cultural, Historic, Archaeological; E – Entry/Owner/Access; O – Other; S – Safety; T – Trustee; X – Exclusion or Security

Additional Site Summary Comments:

Due to the strong tidal currents found near the mouth of this estuary, berm construction is likely the most reliable protection strategy for excluding oil from entering this site. Construction of a berm should be accomplished with the oversight of a local environmental resources manager.

Concerns and Advice to Responders:

Strategically Dynamic: Assess current site conditions before selecting a response strategy or ordering response equipment. Refer to ACP Site 6-000-A for important information on beach nesting birds that use this site. Be prepared to use site monitors to evaluate and minimize any potential negative effects (especially to listed species), that could result from cleanup and response activities at this site.

Hazard and Restrictions:

The river water is known to have elevated bacteria counts that may pose a health threat to responders. Beach access is possible from the north or the south shore using all terrain vehicles. Better access is available from the trail at the visitors center. During summer months California least terns are likely to be nesting on the beach. USFWS must be consulted.

Site Strategies:

Strategy: 6-470.1 Objective: Close the river mouth by constructing a berm across the flow channel.

Strategy: Construct a barrier berm with sand borrowed from the lower beach. Do not use sand from the existing dunes. Consider installing an underflow pipe at the river mouth during seasons when the Tijuana River has moderate or low outflows. The berm may not be an option during high winter outflows.

Table of Response Resources

Equipment	Sub-Type	Size	Unit	QTY	Unit	Last Page Update
Heavy Equipment	Front Loader			1		
Staff	Staff to Deploy			1		

Strategy: 6-470.2 Objective: Boom across the channel to prevent oil movement up-river.

Strategy: Use a skiff to deploy swamp boom and exclude oil from the northern branch of the main channel that leads to Oneonta Slough. There is a pickup truck access path from the park headquarters that can be used to gain access to the boom deployment area.

Table of Response Resources

Equipment	Sub-Type	Size	Unit	QTY	Unit	Last Page Update
Boom	Swamp Boom			150	feet	<i>Strategy Updated:</i>
Anchor	Danforth	15 lb		2		<i>Last Test: 9/16/2014</i>
Vessel	Skiff or Punt			1		
Staff	Staff to Deploy			2		

Strategy: 6-470.3 Objective: Boom across the channel to prevent oil movement up-river.

Strategy: Use a skiff to deploy swamp boom and exclude oil from the channel branch that flows east into the interior of the marsh.

Table of Response Resources

Equipment	Sub-Type	Size	Unit	QTY	Unit	Last Page Update
Boom	Swamp Boom			150	feet	
Anchor	Danforth	15 lb		2		
Vessel	Skiff or Punt			1		
Staff	Staff to Deploy			2		

Strategy: 6-470.4 Objective: Boom across the channel to prevent oil movement up-river.

Strategy: Use a skiff to deploy swamp boom to exclude oil from the channel that flows south from the estuary mouth.

Table of Response Resources

Equipment	Sub-Type	Size	Unit	QTY	Unit	Last Page Update
Boom	Swamp Boom			150	feet	
Anchor	Danforth	15 lb		2		
Vessel	Skiff or Punt			1		

Strategy: 6-470.5 Objective: Prevent oil from entering the wetlands on high tides.

Strategy: When extreme tides threaten to float oil into the low lying pickleweed marsh, install a protective layer of sorbent sweep (or pom poms) on the edge of the pickleweed to minimize the spread of oil into the interior of the marsh. (This strategy is not depicted on the site diagram.)

Table of Response Resources

Equipment	Sub-Type	Size	Unit	QTY	Unit	Last Page Update
Boom	Sorbent Boom			1500	feet	
Anchor	Danforth		15 lb	10		
Vessel	Skiff or Punt			1		
Staff	Staff to Deploy			2		

Logistics:

Directions: The mouth of the Tijuana River can be accessed along the beach face either from the south or north but with restrictions during nesting season. This site is within the following Marine Protected Area: Tijuana River Mouth Marine


Land Access: The mouth of the Tijuana Estuary can be accessed from the north by traveling south on the beach from

On-Water Limitations: Limited water access can be made using hand launched skiffs from a trail near the Tijuana

Facilities, Staging Areas, Command Posts, Available Equipment: Tijuana Estuary Visitor Center 301 Caspian Way,

Communications Problems:

Additional Operational Comments: The Tijuana River mouth is open year-round and subject to flooding following rainstorms. The river divides into three main flow channels, and each channel is handled as a separate prioritized strategy within this plan. Seasonal sand migration in the area may change the desired location(s) for protective boom



Imagery: NAIP 2016, 60 cm resolution