

**SUBSURFACE GEOCHEMICAL ASSESSMENT OF METHANE GAS OCCURRENCES**

**PLAYA VISTA DEVELOPMENT
First Phase Project
Los Angeles, California**

**Prepared for:
CITY OF LOS ANGELES
DEPARTMENT OF BUILDING AND SAFETY**

April 17, 2000

Report Prepared by:

**Exploration Technologies, Inc
3698 Westchase
Houston, TX 77083**

TABLE OF CONTENTS**EXECUTIVE SUMMARY****1.0 INTRODUCTION**

- 1.1 LOCATION
- 1.2 SCOPE OF WORK

2.0 PREVIOUS WORK

- 2.1 GEOTECHNICAL BOREHOLES AND MONITOR WELLS
- 2.2 SOIL GAS SURVEYS
- 2.3 MONITOR WELLS
- 2.4 ISOTOPE ANALYSES
- 2.5 TRACT 03 METHANE ASSESSMENT

3.0 SITE CHARACTERIZATION

- 3.1 TOPOGRAPHY AND SURFACE GEOLOGY
- 3.2 SUBSURFACE GEOLOGY
- 3.3 FAULTS
 - 3.3.1 Charnock Fault
 - 3.3.2 Lincoln Boulevard Fault
- 3.4 SHALLOW NATURAL GAS
 - 3.4.1 Universal City Syndicate, Inc. Vidor #1
 - 3.4.2 Cooperative Development Co. Community #1
 - 3.4.3 Kitselmann Del Rey #1 and Del Rey #2
 - 3.4.4 Mesmer City Realty Co. Well #1

4.0 METHANE ASSESSMENT METHODOLOGIES AND ANALYSES

- 4.1 SOIL GAS SURVEY
- 4.2 SOIL GAS ANALYSES
- 4.3 MONITOR WELL INSTALLATION AND SAMPLING