

STREAM INVENTORY REPORT

Floodgate Creek

INTRODUCTION

A stream inventory was conducted during the summer of 1996 on Floodgate Creek. The inventory was conducted in two parts: habitat inventory and biological inventory. The objective of the habitat inventory was to document the habitat available to anadromous salmonids in Floodgate Creek. The objective of the biological inventory was to document the presence and distribution of juvenile salmonid species.

The objective of this report is to document the current habitat conditions, and recommend options for the potential enhancement of habitat for coho salmon and steelhead trout. Recommendations for habitat improvement activities are based upon target habitat values suitable for salmonids in California's north coast streams.

WATERSHED OVERVIEW

Floodgate Creek is tributary to the Navarro River, tributary to the Pacific Ocean, located in Mendocino County, California (Map 1). Floodgate Creek's legal description at the confluence with Navarro River is T15N R15W S31. Its location is 39°07'14" north latitude and 123°32'47" west longitude. Floodgate Creek is a first order stream and has approximately 2.8 miles of blue line stream according to the USGS Cold Spring 7.5 minute quadrangle. Floodgate Creek drains a watershed of approximately 2.6 square miles. Elevations range from about 100 feet at the mouth of the creek to 400 feet in the headwater areas. Redwood/Douglas fir mixed conifer dominates the watershed. The watershed is entirely privately owned and is managed for timber production. Vehicle access exists via private logging roads.

METHODS

The habitat inventory conducted in Floodgate Creek follows the methodology presented in the *California Salmonid Stream Habitat Restoration Manual* (Flosi and Reynolds, 1991 rev. 1994). The California Conservation Corps (CCC) Technical Advisors and Watershed Stewards Project/AmeriCorps (WSP/AmeriCorps) Members that conducted the inventory were trained in standardized habitat inventory methods by the California Department of Fish and Game (DFG). This inventory was conducted by a two-person team.

SAMPLING STRATEGY

The inventory uses a method that samples approximately 10% of the habitat units within the

survey reach (Hopelain, 1994). All habitat units included in the survey are classified according to habitat type and their lengths are measured. All pool units are measured for maximum depth, depth of pool tail crest, and embeddedness. Habitat unit types encountered for the first time are further measured for all the parameters and characteristics on the field form. Additionally, from the ten habitat units on each field form page, one is randomly selected for complete measurement.

HABITAT INVENTORY COMPONENTS

A standardized habitat inventory form has been developed for use in California stream surveys and can be found in the *California Salmonid Stream Habitat Restoration Manual*. This form was used in Floodgate Creek to record measurements and observations. There are nine components to the inventory form.

1. Flow:

Flow is measured in cubic feet per second (cfs) at the bottom of the stream survey reach using standard flow measuring equipment, if available. In some cases flows are estimated.

2. Channel Type:

Channel typing is conducted according to the classification system developed and revised by David Rosgen (1985 rev. 1994). This methodology is described in the *California Salmonid Stream Habitat Restoration Manual*. Channel typing is conducted simultaneously with habitat typing and follows a standard form to record measurements and observations. There are five measured parameters used to determine channel type: 1) water slope gradient, 2) entrenchment, 3) width/depth ratio, 4) substrate composition, and 5) sinuosity.

3. Temperatures:

Both water and air temperatures are measured and recorded at every tenth habitat unit. The time of the measurement is also recorded. Both temperatures are taken in degrees Fahrenheit at the middle of the habitat unit and within one foot of the water surface.

4. Habitat Type:

Habitat typing uses the 24 habitat classification types defined by McCain and others (1988). Habitat units are numbered sequentially and assigned a type identification number selected from a standard list of 24 habitat types. Dewatered units are labeled "dry". Floodgate Creek habitat typing used standard basin level measurement criteria. These parameters require that the minimum length of a described habitat unit must be equal to or greater than the stream's mean wetted width. Channel dimensions were measured using hip chains, range finders, tape measures, and stadia rods. All units were measured for mean length; additionally, the first occurrence of each unit type and a randomly selected 10% subset of all units were sampled for all

features on the sampling form (Hopelain, 1995). Pool tail crest depth at each pool unit was measured in the thalweg. All measurements were in feet to the nearest tenth.

5. Embeddedness:

The depth of embeddedness of the cobbles in pool tail-out reaches is measured by the percent of the cobble that is surrounded or buried by fine sediment. In Floodgate Creek, embeddedness was ocularly estimated. The values were recorded using the following ranges: 0 - 25% (value 1), 26 - 50% (value 2), 51 - 75% (value 3) and 76 - 100% (value 4). Additionally, a value of 5 was assigned to tail-outs deemed unsuited for spawning due to inappropriate substrate particle size, having a bedrock tail-out, or other considerations.

6. Shelter Rating:

Instream shelter is composed of those elements within a stream channel that provide salmonids protection from predation, reduce water velocities so fish can rest and conserve energy, and allow separation of territorial units to reduce density related competition. The shelter rating is calculated for each fully-described habitat unit by multiplying shelter value and percent cover. Using an overhead view, a quantitative estimate of the percentage of the habitat unit covered is made. All cover is then classified according to a list of nine cover types. In Floodgate Creek, a standard qualitative shelter value of 0 (none), 1 (low), 2 (medium), or 3 (high) was assigned according to the complexity of the cover. Thus, shelter ratings can range from 0-300 and are expressed as mean values by habitat types within a stream.

7. Substrate Composition:

Substrate composition ranges from silt/clay sized particles to boulders and bedrock elements. In all fully-described habitat units, dominant and sub-dominant substrate elements were ocularly estimated using a list of seven size classes and recorded as a one and two respectively.

8. Canopy:

Stream canopy density was estimated using modified handheld spherical densimeters as described in the *California Salmonid Stream Habitat Restoration Manual*. Canopy density relates to the amount of stream shaded from the sun. In Floodgate Creek, an estimate of the percentage of the habitat unit covered by canopy was made from the center of approximately every third unit in addition to every fully-described unit, giving an approximate 30% sub-sample. In addition, the area of canopy was estimated ocularly into percentages of coniferous or deciduous trees.

9. Bank Composition and Vegetation:

Bank composition elements range from bedrock to bare soil. However, the stream banks are usually covered with grass, brush, or trees. These factors influence the ability of stream banks to withstand winter flows. In Floodgate Creek, the dominant composition type and the dominant

vegetation type of both the right and left banks for each fully-described unit were selected from the habitat inventory form. Additionally, the percent of each bank covered by vegetation was estimated and recorded.

BIOLOGICAL INVENTORY

Biological sampling during stream inventory is used to determine fish species and their distribution in the stream. In Floodgate Creek fish presence was observed from the stream banks, and one site was electrofished using a Smith-Root Model 12 electrofisher. These sampling techniques are discussed in the *California Salmonid Stream Habitat Restoration Manual*.

DATA ANALYSIS

Data from the habitat inventory form are entered into Habitat, a dBASE 4.2 data entry program developed by Tim Curtis, Inland Fisheries Division, California Department of Fish and Game. This program processes and summarizes the data, and produces the following six tables:

- Riffle, flatwater, and pool habitat types
- Habitat types and measured parameters
- Pool types
- Maximum pool depths by habitat types
- Dominant substrates by habitat types
- Mean percent shelter by habitat types

Graphics are produced from the tables using Quattro Pro. Graphics developed for Floodgate Creek include:

- Riffle, flatwater, pool habitats by percent occurrence
- Riffle, flatwater, pool habitats by total length
- Total habitat types by percent occurrence
- Pool types by percent occurrence
- Total pools by maximum depths
- Embeddedness
- Pool cover by cover type
- Dominant substrate in low gradient riffles
- Percent canopy
- Bank composition by composition type
- Bank vegetation by vegetation type

HABITAT INVENTORY RESULTS

* ALL TABLES AND GRAPHS ARE LOCATED AT THE END OF THE REPORT *

The habitat inventory of July 24, 1996, was conducted by Andrew MacMillan (WSP\AmeriCorps) and David Jones (CCC). The total length of the stream surveyed was 2,453 feet with an additional 10 feet of side channel.

Flow was measured at the bottom of the survey reach with a Marsh-McBirney Model 2000 flowmeter at 0.01 cfs on July 19, 1996.

Floodgate Creek is an B4 channel type for the entire 2,453 feet of stream reach surveyed. B4 channels are moderately entrenched, moderate gradient, riffle dominated channels with infrequently spaced pools; very stable plan and profile; stable banks; and gravel channel. Water temperatures taken during the survey period ranged from 56 to 58 degrees Fahrenheit. Air temperatures ranged from 70 to 79 degrees Fahrenheit.

Table 1 summarizes the Level II riffle, flatwater, and pool habitat types. Based on frequency of **occurrence** there were 26% riffle units, 14% flatwater units, 48% pool units and 12% was dry (Graph 1). Based on total **length** of Level II habitat types there were 9% riffle units, 15% flatwater units, 51% pool units, and 25% was dry (Graph 2).

Eight Level IV habitat types were identified (Table 2). The most frequent habitat types by percent **occurrence** were low gradient riffles, 26%; mid-channel pools, 22%; and dry , 12% (Graph 3). Based on percent total **length**, dry units made up 25%, mid-channel pools 24%, and glides 11%.

A total of 24 pools were identified (Table 3). Main channel pools were most frequently encountered at 58% and comprised 65% of the total length of all pools (Graph 4).

Table 4 is a summary of maximum pool depths by pool habitat types. Pool quality for salmonids increases with depth. Nine of the twenty-four pools (38%) had a depth of two feet or greater (Graph 5).

The depth of cobble embeddedness was estimated at pool tail-outs. Of the 24 pool tail-outs measured, 2 had a value of 1 (8%); 4 had a value of 2 (17%); 6 had a value of 3 (25%); 3 had a value of 4 (13%) and 9 had a value of 5 (38%) (Graph 6). On this scale, a value of 1 indicates the highest quality of spawning substrate.

A shelter rating was calculated for each habitat unit and expressed as a mean value for each habitat type within the survey using a scale of 0-300. Riffle habitat types had a mean shelter rating of 10, flatwater habitat types had a mean shelter rating of 67, and pool habitats had a mean shelter rating of 32 (Table 1). Of the pool types, the scour pools had the highest mean shelter rating at 34. Main channel pools had a mean shelter rating of 30 (Table 3).

Table 5 summarizes mean percent cover by habitat type. Terrestrial vegetation is the dominant cover type in Floodgate Creek. Graph 7 describes the pool cover in Floodgate Creek.

Table 6 summarizes the dominant substrate by habitat type. Gravel was the dominant substrate

observed in the two low gradient riffles measured (Graph 8).

The mean percent canopy density for the stream reach surveyed was 88%. The mean percentages of deciduous and coniferous trees were 15% and 85%, respectively. Graph 9 describes the canopy in Floodgate Creek.

For the stream reach surveyed, the mean percent right bank vegetated was 56.3%. The mean percent left bank vegetated was 67.5%. The dominant elements composing the structure of the stream banks consisted of 12.5% bedrock, 4.2% boulder, 41.7% cobble/gravel, and 41.7% sand/silt/clay (Graph 10). Deciduous trees were the dominant vegetation type observed in 45.8% of the units surveyed. Additionally, 33.3% of the units surveyed had coniferous trees as the dominant vegetation, including down trees, logs, and root wads (Graph 11).

BIOLOGICAL INVENTORY RESULTS

One site was electrofished on July 24, 1996, in Floodgate Creek. The sites were sampled by Andrew MacMillan (WSP\AmeriCorps) and David Jones (CCC).

The site sampled included habitat units 30 through 34, a mid-channel pool, lateral scour pool - root wad enhanced, and scour pool, approximately 1,053 feet from the confluence with the Navarro River. The site yielded a total 16 steelhead, 1 sculpin and 1 stickleback.

DISCUSSION

Floodgate Creek is a B4 channel type for the entire 2,453 feet of stream surveyed. The suitability of B4 channel types for fish habitat improvement structures is as follows: Excellent for low stage plunge weirs, boulder clusters, bank placed boulders, single and opposing wing deflectors and log cover, and good for medium stage plunge weirs.

The water temperatures recorded on the survey day July 24, 1996, ranged from 56 to 58 degrees Fahrenheit. Air temperatures ranged from 70 to 79 degrees Fahrenheit. This is a good water temperature range for salmonids. To make any further conclusions, temperatures would need to be monitored throughout the warm summer months, and more extensive biological sampling would need to be conducted.

Flatwater habitat types comprised 15% of the total **length** of this survey, riffles 9%, and pools 51%. The pools are relatively shallow, with only 9 of the 24 (38%) pools having a maximum depth greater than 2 feet. In general, pool enhancement projects are considered when primary pools comprise less than 40% of the length of total stream habitat. In first and second order streams, a primary pool is defined to have a maximum depth of at least two feet, occupy at least half the width of the low flow channel, and be as long as the low flow channel width.

Seventeen of the twenty-four pool tail-outs measured had embeddedness ratings of 3, 4 or 5.

Only 2 had a 1 rating. Cobble embeddedness measured to be 25% or less, a rating of 1, is considered to indicate good quality spawning substrate for salmon and steelhead. In Floodgate Creek, sediment sources should be mapped and rated according to their potential sediment yields, and control measures should be taken.

The mean shelter rating for pools was low with a rating of 32. The shelter rating in the flatwater habitats was slightly better at 67. A pool shelter rating of approximately 100 is desirable. The relatively small amount of cover that now exists is being provided primarily by terrestrial vegetation in all habitat types. Additionally, undercut banks contribute a small amount. Log and root wad cover structure in the pool and flatwater habitats are needed to improve both summer and winter salmonid habitat. Log cover structure provides rearing fry with protection from predation, rest from water velocity, and also divides territorial units to reduce density related competition.

The two low gradient riffles measured had gravel as the dominant substrate. This is generally considered good for spawning salmonids.

The mean percent canopy density for the stream was 88%. This is a relatively high percentage of canopy. In general, revegetation projects are considered when canopy density is less than 80%.

The percentage of right and left bank covered with vegetation was moderate at 56.3% and 67.5%, respectively. In areas of stream bank erosion or where bank vegetation is not at acceptable levels, planting endemic species of coniferous and deciduous trees, in conjunction with bank stabilization, is recommended.

RECOMMENDATIONS

- 1) Floodgate Creek should be managed as an anadromous, natural production stream.
- 2) The limited water temperature data available suggest that maximum temperatures are within the acceptable range for juvenile salmonids. To establish more complete and meaningful temperature regime information, 24-hour monitoring during the July and August temperature extreme period should be performed for 3 to 5 years.
- 3) Increase woody cover in the pools and flatwater habitat units. Most of the existing cover is from terrestrial vegetation. Adding high quality complexity with woody cover is desirable.
- 4) Active and potential sediment sources related to the road system need to be identified, mapped, and treated according to their potential for sediment yield to the stream and its tributaries.

COMMENTS AND LANDMARKS

The following landmarks and possible problem sites were noted. All distances are approximate and taken from the beginning of the survey reach.

- 0' Begin survey at confluence with Navarro River. Channel type is B4. The stream channel parallels the Navarro River. This was measured and recorded because the Navarro River has become significantly braided below a large landslide, within which is the confluence of Floodgate Creek and the Navarro River. Floodgate Creek does not empty directly into the Navarro River, but comes out perpendicular to the river, and at the point that it contacts the landslide. It parallels the river for 193 feet before emptying into the Navarro River itself.
- 248' Flatcar bridge for Louisiana-Pacific hauling road, 13' long x 40' wide x 14' high.
- 1,053' Electrofishing site.
- 1,129' Right bank confluence with Colson Gulch, dry. Colson Gulch has a very steep bedrock substrate with a 12' cascade 100' up. It does not appear to be accessible to fish after 100'.
- 2,453' End of survey due to lack of access. Not the end of the anadromous reach.

REFERENCES

- Flosi, G., and F. Reynolds. 1994. California salmonid stream habitat restoration manual, 2nd edition. California Department of Fish and Game, Sacramento, California.
- Hopelain, J. 1995. Sampling levels for fish habitat inventory, unpublished manuscript. California Department of Fish and Game, Inland Fisheries Division, Sacramento, California.

LEVEL III and LEVEL IV HABITAT TYPE KEY

HABITAT TYPE	LETTER	NUMBER
RIFFLE		
Low Gradient Riffle	[LGR]	1.1
High Gradient Riffle	[HGR]	1.2
CASCADE		
Cascade	[CAS]	2.1
Bedrock Sheet	[BRS]	2.2
FLATWATER		
Pocket Water	[POW]	3.1
Glide	[GLD]	3.2
Run	[RUN]	3.3
Step Run	[SRN]	3.4
Edgewater	[EDW]	3.5
MAIN CHANNEL POOLS		
Trench Pool	[TRP]	4.1
Mid-Channel Pool	[MCP]	4.2
Channel Confluence Pool	[CCP]	4.3
Step Pool	[STP]	4.4
SCOUR POOLS		
Corner Pool	[CRP]	5.1
Lateral Scour Pool - Log Enhanced	[LSL]	5.2
Lateral Scour Pool - Root Wad Enhanced	[LSR]	5.3
Lateral Scour Pool - Bedrock Formed	[LSBk]	5.4
Lateral Scour Pool - Boulder Formed	[LSBo]	5.5
Plunge Pool	[PLP]	5.6
BACKWATER POOLS		
Secondary Channel Pool	[SCP]	6.1
Backwater Pool - Boulder Formed	[BPB]	6.2
Backwater Pool - Root Wad Formed	[BPR]	6.3
Backwater Pool - Log Formed	[BPL]	6.4
Dammed Pool	[DPL]	6.5