

## Hazards, Restrictions and Advice for Responders

Consider onsite conditions and the weather forecast before deploying at this site. The suggested boom deployment presumes slow flowing water in Murrieta Creek.

## **Resources-At-Risk**

Ecological: Least Bell's Vireo, Western Spadefoot Toad, Smooth Tarplant

Economic: N/A

**Tribal:** Contact the Native American Heritage Commission at (916) 373-3710 **Cultural and Historic:** Contact the Eastern Information Center at (951) 827-5745

Site Description and Field Notes								
Site Location/Segment:	Site Description and Field Notes: Via Montezuma Road is paved but Murrieta							
MAR-RV-B-005	Creek flows over the road. Deployment of boom or other barrier can be							
	performed by personnel wearing hip waders during low flow conditions.							
Gradient: Low	River Width:	Vehicular	Recreational	Boat Launches:				
	70 m (230 ft)	Access? Yes,	Use? Fishing	Response crews can				
		all vehicles.		launch punts by hand				
				at this site.				
Site Contact/s:	Riverside Co. F	lood Control						
	No Fee Access	Permit						
	(951) 955-1200	)						
	M-F 0800-1700	)						
ESI Shoreline Type:	9B Vegetated low banks							
Site Images								
	-		and the second					

RR = River Right RL = River Left	Photo Date: 1/22/2020
Straight Across	
R	
Upstream	Downstream

Site Objectives: Containment and recovery

Implementation: Deploy boom or Watergate equipment to contain floating oil in Murrieta Creek.

**Staging Area Location and Capabilities/Amenities/Waste Management:** Staging areas may be established on site with a local road closure.

## **Response Strategy Map (overview)**

Page 3 of 3

S



Table of Response Resources							
Туре	Sub-Type	Size	Unit	QTY - Unit	Special Equipment or Comments		
Boom		8	inch	300-feet			
Stakes				6			
Watergate							
Personnel				4			